

Lot 1 progress photos

AUJI-PUNDO ROAD (22.6%)



Before and During



PAMJOS-KANYAMEDHA ROAD (22.1%)



Processing of subgrade 1 Km 0+700-0+800



Field density test for subgrade 1

KOYUGA-KOYOO ROAD (26.2%)



Processing of Subgrade 1 Km 0+660-0+800



Compaction of subgrade 1 Km 0+260-0+360

MOSQUE-KONA MBUTA ROAD (38.6%)



Before



During laying of asphalt

KONA MBUTA-KAEGO ROAD (34.4%)



Before



During compaction of GCS Base layer

WHITE HOUSE- KONA MBAYA (59.4%)

Laying of Asphalt
Concrete at White
House-Kona Mbaya
Road



Asphalt Concrete (AC) done
at White House-Kona
Mbaya Road

KAJANTA-LOVEBAR ROAD (66.0%)

Laying of asphalt concrete (AC)



Asphalt Concrete laid at Kajanta-Lovebar Road



TRANSFORMER- DARAJA MBILI ROAD (32.1%)



Casting of surround for cross culvert at Km 0+290



Compaction of subgrade 2 layer

KAEGO-NEREAH ROAD (1.0%)



Installation of formwork for Culvert wall



Steel fixing for walls and wing walls for the box culvert

KAOMBE-KASAWINO ROAD (27.5%)



Level check for Subgrade 1 Kaombe-Kasawino Road



Proof rolling for subgrade 1 (section passed)

WELLS-WALGUDHA ROAD (29.1%)

Processing of
sub-base layer
Km 0+560-0+750



GCS base layer and
priming of surface
done Km 0+030-
0+180

WATSAN (13%) AND FLOODLIGHT WORKS (10%)



Sewer works



Pad footing and column base casted for the floodlight