

Lot 2 progress photos

LOT 2 PROGRESS PHOTOS (12.1% AND 0.7% RESPECTIVELY)



Compaction of subgrade 1 at Highway Sec-Mama Ngina Road



Compaction of formation layer SDA-Thep thep Road Km 0+090-0+200

LOT 2 PROGRESS PHOTOS



Level check for formation layer Highway Sec School -Mama Ngina Road



Field Density Test for formation layer Highway Sec School-Mama Ngina Road

LOT 2 PROGRESS PHOTOS



Setting out for Nairobi Rd – Kwa Chief- Nairobi Road



Setting out for Nairobi Road-Wings of Change Road